# **Energy Performance Certificate**

**Northern Ireland** 

Non-Domestic Building

2, Toscana Park BANGOR BT19 1FH **Certificate Reference Number:** 

9997-3079-0097-0490-4125

This certificate shows the energy rating of this building. It indicates the energy efficiency of the building fabric and the heating, ventilation, cooling and lighting systems. The rating is compared to two benchmarks for this type of building: one appropriate for new buildings and one appropriate for existing buildings. There is more advice on how to interpret this information on the Department's website www.epb.dfpni.gov.uk.

# **Energy Performance Asset Rating**

More energy efficient



•••• Net zero CO, emissions

 $A_{0-25}$ 

B 26-50

C 51-75

D 76-100

101-125

F 126-150

**G** Over 150

Less energy efficient

### **Technical information**

Main heating fuel:

**Natural Gas** 

**Building environment:** 

Heating and Mechanical Ventilation

Total useful floor area (m<sup>2</sup>):

1732

**Building complexity (NOS level):** 

2

Building emission rate (kgCO<sub>2</sub>/m<sup>2</sup>):

136.87

#### **Benchmarks**

Buildings similar to this one could have ratings as follows:

This is how energy efficient

the building is.

35

If newly built

130

If typical of the existing stock

### Administrative information

This is an Energy Performance Certificate as defined in SR 2008 No.170 as amended

Assessment Software:

DesignBuilder SBEM v3.0.0 using calculation engine SBEM v4.1.c.3

**Property Reference:** 

977014790000

**Assessor Name:** 

Paul Hanna

**Assessor Number:** 

STRO003142

Accreditation Scheme:

Stroma Accreditation

**Employer/Trading Name:** 

Syracuse Associates

Employer/Trading Address:

209 Ballynure Road

Issue Date:

28 Nov 2011

Valid Until:

27 Nov 2021 (unless superseded by a later certificate)

**Related Party Disclosure:** 

Not related to the owner

Recommendations for improving the property are contained in Report Reference Number: 0490-0449-9079-7729-1096

## If you have a complaint or wish to confirm that the certificate is genuine

Details of the assessor and the relevant accreditation scheme are on the certificate. You can get contact details of the accreditation scheme from the Department's website at www.epb.dfpni.gov.uk, together with details of the procedures for confirming authenticity of a certificate and for making a complaint.



For advice on how to take action and to find out about technical and financial assistance schemes to help make buildings more energy efficient visit www.carbontrust.co.uk or call us on 0800 085 2005